

BUILDING SAFETY CERTIFICATE

No : DEE / Bldgs / 09

Dated: 23.01.2025

It is certified that the existing building Pearson School Kompally at Survey No 149 & 150, Kompally, Qutubullapur, Medchal-Malkajigiri-500100. Comprised of **1 Ground Floor + 3 Upper Floors** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)
No. of Floor(s) in the Block	Ground floor +3 Upper Floors with 65000Sft plinth area.

The building is owned/ occupied by Pearson School Kompally Since the year 2012 and Pearson School Kompally, have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Roads and Building department office on 22.01.2025 (date of inspection) in the presence of Peddi Seetharam Reddy S/O late. Peddi Adivi Reddy H No. 5-115, Kompally, Qutubullapur, Medchal-Malkajigiri Dist (name and addresses of the Manager/Secretary or his representative) and that the building / premises is fit for occupancy for running school classes upto X with effect from Academic year 2024-2025 for a period of 3 years in accordance With rule and subject to compliance of the specific conditions as appended (i.e. 2024-2027).

1. The Work has been completed to my best satisfaction
2. The Workmanship & all the materials have been used strictly in accordance with general and details satisfaction.
3. The building is structurally sound, safe and hygienic.
4. Hence it is fit for use how in with Pearson School Kompally is running.

Issued on 23.01.2025 at Medchal- Malkajigiri District by Deputy Executive Engineer (R&B)- Buildings Sub-Division.

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: N. Srinivasan

Name: N. Srinivasan

Designation: _____

Name & Address of Department/Office: _____
Dy. Executive Engineer (R&B)
Buildings Sub-Division
Medchal-Malkajigiri (Division)
Medchal-Malkajigiri (Dist.)